Annexure D

BUILDING SAFETY CERTIFICATE

No. AEE.PWD:SDL:TB/BSC/2025-26/383

Dated:23-06-2025

It is certified that the existing building 4-4-118/282/B-37 at Bhamasagar Colony Lingasugur Road, Mudgal is having block(s)/Floor(s) as per details below:

Detail of Block(s)in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s)in the Block	One Block – Zero basement, Ground floor and one upper floor	Nil	Nil	Nil	Nil	Nil

The building is owned/occupied by Dr S.B Bhamasagar Public School, Mudgal have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Pulic work department on 16-06-2025 in the presence of Secretary Dr.Sanjeev Bhamasagar and the that the building / premises is fit for occupancy for running school with effect from 23-06-2025 for a period of one year in accordance with rule and subject to compliance of the specific conditions as appended.

- 1. To report immediately report to the competent authority if any problem of collapse/ crack/ water leakage etc. is found n any part of the building in the next few days.
- 2. Proper maintenance of original building document.
- 3. The said building is coming up in an Urban area and according to the government circular for issue of building safety certificate Rs 5000/- to be paid to this office.

Issued on 23-06-2025 at. Asst. Executive Engineer, Sub Division Lingasugur by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name:

Designation: Sub Division Lingasugur Name & Address of Department/ Office: Assistant Executive Engineer

_Sub Division Lingasugunೀಯರರು ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಉಪ-ವಿಭಾಗ

ಲಿಗಸುಗೂರು.

To

The Principal

Dr SB Bhamasagar Public School Lingasagur Road, Mudgal

Secretary

Dr. S.B. Bhamasagar Memorial Trust (R)

Dr. S.B. BHAMASAGAR PUBL SCHOOL, MUDGAL-58412

Reg. No. LNG-4-00176 MUDGAL - 584 125.

Tq. Lingasugur,

Dist. Raichur