

BUILDING SAFETY CERTIFICATE

No. AEE.PWD:SDL:TB/BSC/103

Dated: -11/09/2026

It is certified that the existing building 4-4-118/282/B-37 at Bhamasagar Colony Lingasugur Road, Mudgal is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	One Block - Zero basement, Ground floor and two upper floors	Nil	Nil	Nil	Nil	Nil

The building is owned/occupied by **Dr S.B Bhamasagar Public School, Mudgal** have complied with the Building safety requirements in accordance with National Building Code Rules, and verified by the officers concerned of Public Work Department on 08-09-2026 in the presence of Secretary Dr. Sanjeev Bhamasagar and that the building / premises is fit for occupancy for running school with effect from 09-09-2026 for a period of three(3) years in accordance with rule and subject to compliance of the specific conditions as appended.

Specific Conditions:

1. To report immediately to the competent authority if any problem of collapse / crack / water leakage etc. is found in any part of the building in the next few days.
2. Proper maintenance of original building document.
3. The said building is coming up in an Urban area and according to the government circular for issue of building safety certificate Rs 5000/- to be paid to this office.

Issued on 09-09-2026 at Asst. Executive Engineer, Sub Division Lingasugur by

To
The Principal
Dr SB Bhamasagar Public School
Lingasugur Road, Mudgal
Tq. Lingasugur, Dist. Raichur

Signature with Seal

Name: ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಇಂಜಿನಿಯರ್
Designation: Sub Division Lingasugur
Name & Address of Department / Office:
Assistant Executive Engineer Sub Division,
Lingasugur